

DATA CHAMBERS ON BOTH 9R AND 9L INTERMITTENTLY OUT OF FOCUS BEGINNING AT EXPOSURE NR 1821. BOTH 9L AND 9R FRAMES INTERMITTENTLY OUT OF FOCUS FROM INNER EDGE AND EXTENDING INTO APPROXIMATE CENTER OF 9 INCH FRAME WITH FOCUS BECOMING BETTER AS IT APPROACHES OUTSIDE CENTER OF FRAME. APPARENT CAUSE, VACUUM FAILURE. FILM CREASE DUE

TO FOLD IN PROCESSOR DRY BOX (HTA/2), FROM FRAME NR 931 TO 938, 9L. SMALL TEARS FRAME NRS 269, 271, 273, 9L DUE TO SP 10/70

PRINTER MALFUNCTION. DESENSITIZED SPOTS REPORTED IN PREVIOUS

Approved For Release 2002/10/31 CIA RDP89B00569R000200140003-5
REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

GROUP I

Approved For Release 2002/10/31: CIA-RDP89B00569R000200140003-5

X1Δ

SECRET

(IN 63268)

PAGE TWO

20 REPORTS NO LONGER IN EVIDENCE. METERING GOOD.

- 7. NOT ACCOMPLISHED
- 8. TAKE TO BE FORWARDED BY COURIER APPROX 1900 LOCAL, 22 JAN 1963.
  END OF MESSAGE